Holly Lodge Cottage Review Photographs 5th March 2018



Combination Boiler

A new combination boiler has been fitted late 2017; serving all hot water in the lodge accommodation.



Deadleg Pipe Work

Deadleg pipe work was still seen on the mains water pipe work in the rear bedroom cupboard space; recommend removal. Capped off pipe work seen investigate and remove if found to be live.



Possible Deadleg Pipe Work

Capped off pipe work was still seen in the rear bedroom cupboard space area; investigate and remove if found to be live.



Electric Shower

A new electric shower has recently been installed; this shower gets regular usage.



Showerhead

The showerhead is being cleaned and descaled at least on a quarterly basis; this was last carried out in January 2018 and was seen recorded in the logbook documentation.