

6 Out of Tolerance Result and Action Record

Date	Record No.	System / Location	Type of Out of Tolerance
15/12/2014	0139	Cold water system in Scola Block	Poor cold water flow at outlets in Scola disabled toilet, staff gent's toilet and CDT toilet; creating elevated cold water temperatures..
15/12/2014	0140	Kitchen hot water calorifiers.	Both calorifiers were found to have tripped out; no hot water available.
15/12/2014	0141	Hot water system badminton Block.	No.2 calorifier storage temperature was still found to be below the recommended 60.0c.
15/12/2014	0142	Hot water in Rothely nursery	Hot water return temperature was found to be below the recommended 50.0c.

Record No.	Action Required	Action Completed	Signature
0139	Investigate cold water system in Scola block areas noted above as poor flow at outlets; ensure system opened up correctly.		
0140	Find fault with both calorifiers and ensure heated to maintain 60.0c or more storage temperature in both vessels.		
0141	Raise No.2 hot water calorifier storage temperature to store hot water at 60.0c or more.		
0142	Investigate Rothely nursery calorifier return pump for correct operation; ensure system maintains 50.0c or more at all times.		

Continue with weekly flushing of infrequently used outlets and record when carried out.