

**Church View (Old Itech Centre)**

**Review Photographs**

**8<sup>th</sup> August 2017**



## Water Heater

The water heater within the ladies group room toilet had low storage temperature at the time of this 2017 review; records seen indicate this is normally satisfactory.



## Water Heater

The water heater within the ladies toilet had a good storage temperature at the time of this 2017 review; records seen indicate this is normally satisfactory.



## Water Heater

The water heater within the kitchen area had a good storage temperature at the time of this 2017 review; records seen indicate this is normally satisfactory.



## **Insulated Pipe work**

The domestic water pipe work running in the ceiling voids was seen to be well insulated to help prevent heat gain / loss.



## TMVs

There are two TMVs located within the kitchen area; these were last serviced and adjusted in March 2016 this was seen recorded within the logbook documentation at the time of this 2017 review.



## **Scale Build Up**

Ensure all tap outlets within the building are cleaned and descaled on a regular basis as this is an ideal nutrient for bacteria proliferation.