

**Redbridge Primary School**

**Review Photographs**

**10<sup>th</sup> February 2017**



## Hot Water Calorifier

The hot water calorifier serving all hot water outlets in the school was found to have good storage and return temperatures; records seen indicate these are normally good.



## **Accessible Toilet Shower**

The accessible toilet shower is being flushed on a weekly basis and this is being recorded in the site managers folder located in the site managers office.



## Showerhead

The accessible toilet showerhead is being cleaned on a quarterly basis by the site manager; this is being recorded in the site managers folder located in the site managers office when carried out.



## **TMV Tap Outlets**

TMVs within the school are being serviced and maintained on a six monthly basis; this is recorded in the water systems logbook when carried out. Records seen at the time of this 2017 review indicate this was last carried out in August 2016.



## **Inline Strainers**

Inline strainers are fitted on supplies to the TMV taps; these should be cleaned as part of the service and maintenance schedule as these are ideal areas for bacteria proliferation; no records were seen at the time of this 2017 review to indicate this is being carried out.



## TMVs

TMVs within the school are being serviced and maintained on a six monthly basis; this is recorded in the water systems logbook when carried out. Records seen at the time of this 2017 review indicate this was last carried out in August 2016.



## **Scale on Tap Outlets**

Ensure tap outlets are cleaned on a regular basis to prevent scale build up as this can act as a nutrient for bacteria proliferation.





## **Water Butts**

Water butts are being used to store water for watering flowers etc; ensure the water barrels are cleaned out on a regular basis as ideal areas for bacteria proliferation.



## Insulation

Domestic water pipe runs within the school were seen to be well insulated to protect from heat gain / loss.