

Schools Library Service Building

Review Photographs

7th March 2018



Kitchen Local Water Heater

With a capacity more than 15 litres the water heater should store hot water at 60.0C; slightly low at the time of this 2018 review.



Kitchen Local Water Heater

Internal view of the kitchen local water heater proves a build up of sediment; recommend the header tank is cleaned and disinfected and continued annually if required.



Local Water Heater

The local water heater serving the first floor toilet outlets had a good storage temperature at the time of this 2018 review.



Deadleg Pipe Work Fire Hose Reels

The fire hose reels are supplied by the mains water service; it has been recommended that these fire hose reels be removed to prevent deadleg pipe work; these are still in place on the ground and first floors.