

6 Out of Tolerance Result and Action Record

Date	Record No.	System / Location	Type of Out of Tolerance
03/07/2014	0124	Hot water system Scola junior girls toilet	Hot water did not achieve 50.0c at the outlets within one minute.
03/07/2014	0125	CDT toilet area Scola block disabled toilet. Science block right hand classroom.	Elevated cold water temperatures.

Record No.	Action Required	Action Completed	Signature
0124	Investigate hot water system to toilet outlets ensure system opened up correctly.		
0125	Ensure these areas are included in weekly flushing; and pipe runs are insulated to help prevent heat gain on cold water pipe runs.		

Continue with weekly flushing of infrequently used outlets and record when carried out.



FRESTON
 Water Treatment