

8. Sentinel Hot & Cold Outlet Temperature Record

Cold water temperatures – check that temperature is below 20°C after running the water for up to 2 minutes

Hot water temperatures - check water temperature up to one minute to see if it has reached 50°C

Hot water supply temperature to TMV - check water temperature up to one minute to see if it has reached 50°C

Date	Location – Old School Building	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
15/12/2014	Visitors female wc	28.0	9.0	-	No	PS
15/12/2014	Cleaners Cupboard	31.0	9.5		No	PS
15/12/2014	Reception Tea Bay	55.2	9.5	-	Yes	PS
15/12/2014	Caretakers Workshop	56.5	9.0	-	Yes	PS

Date	Location – Scola Block	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
15/12/2014	Food tech room 26	57.6	19.8	-	Yes	PS
15/12/2014	Art room 33 – main block 2 nd floor	65.1	12.9	-	Yes	PS
15/12/2014	Room 20 - Science block	51.8	10.9	-	Yes	PS
15/12/2014	Disabled changing Room (mixer tap)	61.5	21.6	40.6	No	PS
15/12/2014	Cleaners room	No Access				PS
15/12/2014	Female staff Room Toilet	64.2	12.5	-	Yes	PS

Date	Location – Sports Hall & Badminton	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
15/12/2014	*Ground level - Coffee shop & Kitchen	58.2	9.9	-	Yes	PS
15/12/2014	Lower level – Cleaners room	59.0	10.4	-	Yes	PS
15/12/2014	Lower level – 1 st aid room	No Access				PS

Date	Location – Science & Maths Block	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
15/12/2014	Store room	66.2	17.4		Yes	PS
15/12/2014	'right' classroom	67.3	18.8		Yes	PS

Date	Location – Main kitchen block	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
15/12/2014	Kitchen	Tripped No Hot	10.2	-	No	PS

Date	Location –New Rothely Nursery Building	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
15/12/2014	Staff Room	52.9	8.5		Yes	PS
15/12/2014	Changing Room	53.6	8.8		Yes	PS
15/12/2014	Pre-School WC	52.0	7.9	39.2	Yes	PS