

8. Sentinel Hot & Cold Outlet Temperature Record

Cold water temperatures – check that temperature is below 20°C after running the water for up to 2 minutes

Hot water temperatures - check water temperature up to one minute to see if it has reached 50°C

Hot water supply temperature to TMV - check water temperature up to one minute to see if it has reached 50°C

Date	Location – Old School Building	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
07/11/2014	Visitors female wc	53.5	13.0	-	Yes	PS
07/11/2014	Cleaners Cupboard	57.5	13.2		Yes	PS
07/11/2014	Reception Tea Bay	64.2	13.3	-	Yes	PS
07/11/2014	Caretakers Workshop	60.0	12.6	-	Yes	PS

Date	Location – Scola Block	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
07/11/2014	Food tech room 26	56.0	19.8	-	Yes	PS
07/11/2014	Art room 33 – main block 2 nd floor	65.0	14.9	-	Yes	PS
07/11/2014	Room 20 - Science block	48.3	15.2	-	No	PS
07/11/2014	Disabled changing Room (mixer tap)	63.0	21.8	42.8	No	PS
07/11/2014	Cleaners room	64.3	18.8		Yes	PS
07/11/2014	Female staff Room Toilet	64.2	14.9	-	Yes	PS

Date	Location – Sports Hall & Badminton	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
07/11/2014	*Ground level - Coffee shop & Kitchen	56.8	14.1	-	Yes	PS
07/11/2014	Lower level – Cleaners room	58.5	14.1	-	Yes	PS
07/11/2014	Lower level – 1 st aid room	No Access				PS

Date	Location – Science & Maths Block	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
07/11/2014	Store room	64.8	17.6		Yes	PS
07/11/2014	'right' classroom	66.4	19.9		Yes	PS

Date	Location – Main kitchen block	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
07/11/2014	Kitchen	60.0	12.8	-	Yes	PS

Date	Location –New Rothely Nursery Building	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
07/11/2014	Staff Room	51.3	13.1		Yes	PS
07/11/2014	Changing Room	59.4	12.9		Yes	PS
07/11/2014	Pre-School WC	62.9	12.9	31.0	Yes	PS