

8. Sentinel Hot & Cold Outlet Temperature Record

Cold water temperatures – check that temperature is below 20°C after running the water for up to 2 minutes

Hot water temperatures - check water temperature up to one minute to see if it has reached 50°C

Hot water supply temperature to TMV - check water temperature up to one minute to see if it has reached 50°C

Date	Location – Old School Building	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
03/10/2014	Visitors female wc	56.2	15.6	-	Yes	PS
03/10/2014	Cleaners Cupboard	59.0	15.3		Yes	PS
03/10/2014	Reception Tea Bay	55.6	15.5	-	Yes	PS
03/10/2014	Caretakers Workshop	58.6	15.6	-	Yes	PS

Date	Location – Scola Block	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
03/10/2014	Food tech room 26	57.0	19.8	-	Yes	PS
03/10/2014	Art room 33 – main block 2 nd floor	63.2	16.7	-	Yes	PS
03/10/2014	Room 20 - Science block	58.0	17.4	-	Yes	PS
03/10/2014	Disabled changing Room (mixer tap)	61.0	22.5	42.7	No	PS
03/10/2014	Cleaners room	64.0	18.2		Yes	PS
03/10/2014	Female staff Room Toilet	64.0	16.8	-	Yes	PS

Date	Location – Sports Hall & Badminton	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
03/10/2014	*Ground level - Coffee shop & Kitchen	57.0	16.0	-	Yes	PS
03/10/2014	Lower level – Cleaners room	No Access		-		PS
03/10/2014	Lower level – 1 st aid room	No Access				PS

Date	Location – Science & Maths Block	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
03/10/2014	Store room	66.3	19.6		Yes	PS
03/10/2014	'right' classroom	67.5	22.0		No	PS

Date	Location – Main kitchen block	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
03/10/2014	Kitchen	72.4	16.3	-	Yes	PS

Date	Location –New Rothely Nursery Building	Hot °C	Cold °C	TMV °C	Temperature satisfactory	Initial
03/10/2014	Staff Room	31.0	15.5		No	PS
03/10/2014	Changing Room	31.0	15.7		No	PS
03/10/2014	Pre-School WC	31.0	15.8	31.0	No	PS